Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

CG410 10 BOUCK CT. NY Spills S102146694
NNE 10 BOUCK CT N/A

1/2-1 BROOKLYN, NY

0.648 mi.

3424 ft. Site 3 of 3 in cluster CG

 Relative:
 SPILLS:

 Higher
 Name:
 JUNK YARD

 Actual:
 Address:
 10 BOUCK CT

 13 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 9302128 / 1993-05-17

 Facility ID:
 9302128

 Facility Type:
 ER

 DER Facility ID:
 113997

 Site ID:
 132385

DEC Region: 2

Spill Cause: Unknown Spill Class: Π4 SWIS: 2401 Spill Date: 1993-05-15 Investigator: **MCTIBBE** Referred To: Not reported Reported to Dept: 1993-05-15 CID: Not reported Water Affected: Not reported Spill Source: Unknown Spill Notifier: Local Agency Cleanup Ceased: 1993-05-17 Cleanup Meets Std: True Last Inspection: Not reported Recommended Penalty: False **UST Trust**: False Remediation Phase:

Date Entered In Computer: 1993-05-19
Spill Record Last Update: 2003-03-17
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

LIBBE .

Remarks: "OIL IS FLOWING OUT OF GROUND INTO SEWER. HIRE CONTRACTOR TO

INVESTIGATE.DEP SAID THAT THE OIL IS NOT COMING OUT."

All Materials:

 Site ID:
 132385

 Operable Unit ID:
 984142

 Operable Unit:
 01

 Material ID:
 399267

 Material Code:
 0066A

Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: L
Recovered: .00

Oxygenate: Not reported

Map ID MAP FINDINGS

Direction Distance Elevation

stance EDR ID Number evation Site Database(s) EPA ID Number

 Name:
 10 BOUCK CT.

 Address:
 10 BOUCK CT

 City, State, Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 9304063 / 1993-06-30

Facility ID: 9304063 Facility Type: ER DER Facility ID: 113997 132386 Site ID: DEC Region: 2 Spill Cause: Deliberate Spill Class: D4 SWIS: 2401 Spill Date: 1993-06-16 Investigator: CAMMISA Referred To: Not reported Reported to Dept: 1993-06-30 Not reported CID: Water Affected: Not reported Spill Source:

Spill Source: Commercial/Industrial Spill Notifier: Federal Government

Cleanup Ceased: 1993-06-30
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 1993-07-01
Spill Record Last Update: 1993-07-20
Spiller Name: Not reported

Spiller Company: LEVINE JUMK YARD

Spiller Address: Not reported

Spiller Company: 001

Contact Name: Not reported

DEC Memo:

Remarks: "DUMPING OIL FROM JUMK CARS ON LAND. CALLER WOULD LIKE A CALL BACK ON

THIS. DEP HAS A PROGRAM FOR THIS SITE."

All Materials:

 Site ID:
 132386

 Operable Unit ID:
 982344

 Operable Unit:
 01

 Material ID:
 397594

 Material Code:
 0022

Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00

Units: Not reported

Recovered: .00

Oxygenate: Not reported